

SP50DS User Guide



Model Number SP50DS

- 60 meters Semi Rigid Pushrod
- Colour Camera Self Uprighting
- LED Light Ring
- SD Card Recording in MPEG4
- Meterage Counter
- 100mm and 150mm Camera Skids

SP50DS

The SP50DS can be turned on using the switch underneath the unit. When switched on, the camera lights will illuminate and the screen will display the DVR information before displaying the camera picture.

- Insert an SD card into the slot at the bottom left of the unit.
- To start recording, press **REC**. The OSD will display a REC.
- To stop recording, press the **Stop** button.
- To record a still image, press the **Camera** button.

To Review Files:

- Press the **Folder / Del** button - the folder name will display.
- Press the **REC / SEL** button to select the folder and view files.
- Using the **Up / Down Arrows** select a file, *NOTE* all recorded files will end in -1. (-2 will be blank)
- Press the **Play / Pause** button to play the file on the screen.
- To return to live picture press **ESC / Preview**.

The System battery is charged via a DC Socket on the rear of the unit. We suggest charging daily.

Meterage OSD is displayed top right of the screen.

To reset the count, press the reset button located bottom centre of the unit.

This system is only compatible with AM Industrial equipment, do not attempt to plug the monitor into any other equipment.

